
























Inspected By :			Audited By: Kobac		
Inspected Time: 2011-03-27 4:53 PM			Inspected Location: Domovinski most		
File Name	IR000158.JPG	Created Date	3/26/2011	Created Time	5:34:35 PM
Emissivity	1	Humidity	70%	Min Temp	24,8°C
Ambient	22,3°C	Max Temp	56,7°C		
IR Image				Object Parameter	Value
				Max	56,7°C
				Max:Emissivity	1,00
				Min	24,8°C
				Min:Emissivity	1,00
				L1:AvgTemp	48,7°C
				L1:MaxTemp	55,9°C
				L1:MinTemp	26,9°C
				L1:Emissivity	1,00
Visible Image					
Profile					
Analysis & Recommended Action:					

<b>Inspected By :</b>			<b>Audited By:</b> Kobac																				
<b>Inspected Time:</b> 2011-03-27 4:58 PM			<b>Inspected Location:</b> Domovinski most																				
<b>File Name</b>	IR000159.JPG	<b>Created Date</b>	3/26/2011	<b>Created Time</b>	5:35:35 PM																		
<b>Emissivity</b>	1	<b>Humidity</b>	70%	<b>Min Temp</b>	24,8°C																		
<b>Ambient</b>	22,4°C	<b>Max Temp</b>	60,2°C																				
<b>IR Image</b>				<table border="1"> <thead> <tr> <th>Object Parameter</th> <th>Value</th> </tr> </thead> <tbody> <tr> <td>Max</td> <td>60,2°C</td> </tr> <tr> <td>Max:Emissivity</td> <td>1,00</td> </tr> <tr> <td>Min</td> <td>24,8°C</td> </tr> <tr> <td>Min:Emissivity</td> <td>1,00</td> </tr> <tr> <td>L1:AvgTemp</td> <td>57,6°C</td> </tr> <tr> <td>L1:MaxTemp</td> <td>60,2°C</td> </tr> <tr> <td>L1:MinTemp</td> <td>44,7°C</td> </tr> <tr> <td>L1:Emissivity</td> <td>1,00</td> </tr> </tbody> </table>		Object Parameter	Value	Max	60,2°C	Max:Emissivity	1,00	Min	24,8°C	Min:Emissivity	1,00	L1:AvgTemp	57,6°C	L1:MaxTemp	60,2°C	L1:MinTemp	44,7°C	L1:Emissivity	1,00
Object Parameter	Value																						
Max	60,2°C																						
Max:Emissivity	1,00																						
Min	24,8°C																						
Min:Emissivity	1,00																						
L1:AvgTemp	57,6°C																						
L1:MaxTemp	60,2°C																						
L1:MinTemp	44,7°C																						
L1:Emissivity	1,00																						
<b>Visible Image</b>				<p><b>Histogram - L1</b></p> 																			
<b>Profile</b>																							
<b>Analysis &amp; Recommended Action:</b>																							




Inspected By :			Audited By: Kobac						
Inspected Time: 2011-03-27 5:01 PM			Inspected Location: Domovinski most						
File Name	IR000160.JPG	Created Date	3/26/2011	Created Time	5:40:33 PM				
Emissivity	1	Humidity	70%	Min Temp	19,5°C				
Ambient	22,9°C	Max Temp	46,7°C						
IR Image				Object Parameter	Value				
				Max	46,7°C				
				Max:Emissivity	1,00				
				Min	19,5°C				
				Min:Emissivity	1,00				
				L1:AvgTemp	44,5°C				
				L1:MaxTemp	46,3°C				
				L1:MinTemp	32,6°C				
				L1:Emissivity	1,00				
				L2:AvgTemp	43,4°C				
				L2:MaxTemp	44,2°C				
				L2:MinTemp	38,6°C				
				L2:Emissivity	1,00				
				Visible Image				Histogram - L1	
									
Histogram - L2									
									
Profile									
Analysis & Recommended Action:									




Inspected By :			Audited By: Kobac		
Inspected Time: 2011-03-27 5:19 PM			Inspected Location: Domovinski most		
File Name	IR000166.JPG	Created Date	3/26/2011	Created Time	5:54:27 PM
Emissivity	1	Humidity	70%	Min Temp	22,9°C
Ambient	22,7°C	Max Temp	49,6°C		
IR Image				Object Parameter	Value
				Max	49,6°C
				Max:Emissivity	1,00
				Min	22,9°C
				Min:Emissivity	1,00
				L1:AvgTemp	47,3°C
				L1:MaxTemp	48,9°C
				L1:MinTemp	27,4°C
				L1:Emissivity	1,00
				L2:AvgTemp	47,8°C
				L2:MaxTemp	48,9°C
				L2:MinTemp	40,7°C
				L2:Emissivity	1,00
				Visible Image	
Profile					
Analysis & Recommended Action:					

Inspected By :			Audited By: Kobac						
Inspected Time: 2011-03-27 5:05 PM			Inspected Location: Domovinski most						
File Name	IR000161.JPG	Created Date	3/26/2011	Created Time	5:40:33 PM				
Emissivity	1	Humidity	70%	Min Temp	20,0°C				
Ambient	22,9°C	Max Temp	49,0°C						
IR Image				Object Parameter	Value				
				Max	49,0°C				
				Max:Emissivity	1,00				
				Min	20,0°C				
				Min:Emissivity	1,00				
				L1:AvgTemp	43,4°C				
				L1:MaxTemp	48,8°C				
				L1:MinTemp	30,2°C				
				L1:Emissivity	1,00				
				L2:AvgTemp	48,7°C				
				L2:MaxTemp	48,8°C				
				L2:MinTemp	39,7°C				
				L2:Emissivity	1,00				
Visible Image				Histogram - L1					
									
				Histogram - L2					
									
				Profile					
Analysis & Recommended Action:									




Inspected By :			Audited By: Kobac		
Inspected Time: 2011-03-27 5:10 PM			Inspected Location: Domovinski most		
File Name	IR000162.JPG	Created Date	3/26/2011	Created Time	5:40:33 PM
Emissivity	1	Humidity	70%	Min Temp	16,8°C
Ambient	22,7°C	Max Temp	50,2°C		
IR Image				Object Parameter	Value
				Max	50,2°C
				Max:Emissivity	1,00
				Min	16,8°C
				Min:Emissivity	1,00
				L1:AvgTemp	30,0°C
				L1:MaxTemp	32,1°C
				L1:MinTemp	25,9°C
				L1:Emissivity	1,00
Visible Image					
Profile					
Analysis & Recommended Action:					



Inspected By :			Audited By: Kobac		
Inspected Time: 2011-03-27 5:12 PM			Inspected Location: Domovinski most		
File Name	IR000163.JPG	Created Date	3/26/2011	Created Time	5:40:33 PM
Emissivity	1	Humidity	70%	Min Temp	17,2°C
Ambient	22,6°C	Max Temp	50,5°C		
IR Image				Object Parameter	Value
				Max	50,5°C
				Max:Emissivity	1,00
				Min	17,2°C
				Min:Emissivity	1,00
				L1:AvgTemp	46,2°C
				L1:MaxTemp	50,4°C
				L1:MinTemp	35,3°C
				L1:Emissivity	1,00
Visible Image					
Profile					
Analysis & Recommended Action:					

<b>Inspected By :</b>			<b>Audited By:</b> Kobac																				
<b>Inspected Time:</b> 2011-03-27 5:14 PM			<b>Inspected Location:</b> Domovinski most																				
<b>File Name</b>	IR000164.JPG	<b>Created Date</b>	3/26/2011	<b>Created Time</b>	5:40:33 PM																		
<b>Emissivity</b>	1	<b>Humidity</b>	70%	<b>Min Temp</b>	20,8°C																		
<b>Ambient</b>	22,6°C	<b>Max Temp</b>	35,8°C																				
<b>IR Image</b>				<table border="1"> <thead> <tr> <th>Object Parameter</th> <th>Value</th> </tr> </thead> <tbody> <tr> <td>Max</td> <td>35,8°C</td> </tr> <tr> <td>Max:Emissivity</td> <td>1,00</td> </tr> <tr> <td>Min</td> <td>20,8°C</td> </tr> <tr> <td>Min:Emissivity</td> <td>1,00</td> </tr> <tr> <td>L1:AvgTemp</td> <td>33,3°C</td> </tr> <tr> <td>L1:MaxTemp</td> <td>35,8°C</td> </tr> <tr> <td>L1:MinTemp</td> <td>24,3°C</td> </tr> <tr> <td>L1:Emissivity</td> <td>1,00</td> </tr> </tbody> </table>		Object Parameter	Value	Max	35,8°C	Max:Emissivity	1,00	Min	20,8°C	Min:Emissivity	1,00	L1:AvgTemp	33,3°C	L1:MaxTemp	35,8°C	L1:MinTemp	24,3°C	L1:Emissivity	1,00
Object Parameter	Value																						
Max	35,8°C																						
Max:Emissivity	1,00																						
Min	20,8°C																						
Min:Emissivity	1,00																						
L1:AvgTemp	33,3°C																						
L1:MaxTemp	35,8°C																						
L1:MinTemp	24,3°C																						
L1:Emissivity	1,00																						
<b>Visible Image</b>																							
<b>Profile</b>																							
<b>Analysis &amp; Recommended Action:</b>																							



Inspected By :			Audited By: Kobac		
Inspected Time: 2011-03-27 5:16 PM			Inspected Location: Domovinski most		
File Name	IR000165.JPG	Created Date	3/26/2011	Created Time	5:54:27 PM
Emissivity	1	Humidity	70%	Min Temp	23,7°C
Ambient	22,9°C	Max Temp	50,2°C		
IR Image				Object Parameter	Value
				Max	50,2°C
				Max:Emissivity	1,00
				Min	23,7°C
				Min:Emissivity	1,00
				L1:AvgTemp	45,0°C
				L1:MaxTemp	49,9°C
				L1:MinTemp	25,7°C
				L1:Emissivity	1,00
Visible Image					
Profile					
Analysis & Recommended Action:					